



# morton.

Located at the northern end of the award-winning Sydney Wharf, designed by the acclaimed PTW architects, this furnished unique apartment offers easy entertaining and a bespoke city lifestyle.

- Oversized one bedroom with 78sqm internal, 110 sqm in total

- Stunning designer furnishings throughout
- Enjoying sprawling water views from every room
- Light filled open plan living area flows onto the large balcony
- Large master bedroom
- Travetine Bathrooms and superbly finished cabinetry
- Stylish marble kitchen features exquisite island bench
- Miele Gas appliances, ducted air conditioning
- Security parking in basement and Concierge services.
- Facilities including gym, pool and spa.

### Pyrmont 51/56 Pirrama Road □ 1 🔓 1 😭 1

#### View

As advertised or by appointment

#### Agent


Patricia Carter

0456 880 004

patricia@morton.com.au

## morton.com.au

#### SYDNEY WHARF 9



# 9.1.51


SYDNEY WHARF 9 PYRMONT BAY 1 BEDROOM

3.7 x 4.4m	LMing
2.9 x 4.4m	Dining
3.2 x 3.7m	Bedroom 1

Note:

Floor plana are drawn at an unspecified scale.
Room sizes of Bedrooms are taken to the front face of robe.

- Under bench oven in Kitchen.



LEVEL 1

December The Lag state only and west prepared prior to completion of the project. This information contributed herein its belowed to be cannot, wreak, they and west prepared as changes will understandy occur during the development, directions, west, they a fully a fully a state of a specification in the development and the provisions of the Contract be bain. Buffered to here an ord depleted to the tracket of the Contract be bain. Buffered to here an ord depleted to the tracket of the Contract be bain. Buffered to the contract of the Contract be bain. Buffered to necessary for senders are not depleted. The induced optical in the Layout Pien is not induced in the rate. The postfor of the Landow should be the senders and the layout Pien is not induced in the senders. The postfor of the Landow should be the senders and the layout Pien is not induced in the rate. The postfor of the Landow should be the layout Pien is not induced in the senders.